



Map 3. GREAT BROOK TRAIL INVENTORY AND MAINTENANCE NEEDS

1	Stream crossing (relatively narrow and shallow)
2	20' decayed log bridge - needs removal and replacement
3	Stream crossing (relatively narrow and shallow)
4	25' decaying log bridge - needs repair or replacement
5	Side trail - needs sign to indicate if access is allowed
6	Twin Rocks intersection - trail indistinct

-  Maintenance Needs (see table)
-  Photo Locations

Deerfield, NH Trail Inventory  
August 2011

